


Compensation Curve



(Base ambient Temp. 40°C)	-10	0	10	20	30	40	50	60
(Base ambient Temp. 50°C)	-5	5	15	25	35	45	55	

Ambient Temperature °C